

State of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

September 11, 2008

Reviewed MY

Mine Name:Robert Harris- ML 26068	Permit Number: S0270065 Inspection Date: 07/17/2007		
Operator Name: Robert L Harris			
Inspector(s): T Munson	Time : 11:00-12 noon		
Other Participants: None	Mine Status: active		

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds			
2. Public Safety (shafts, adits, trash, signs, highwalls)			
3. Protection of Drainages / Erosion Control			
4. Deleterious Material	\boxtimes		
5. Roads (maintenance, surfacing, dust control, safety)			
6. Reclamation			
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)			
8. Soils			
9. Revegetation			

Bond Renewal Date: Bond to be reviewed. Bond Amount: \$ 7,621 Permit fee is up to date

Purpose of Inspection: Routine annual Inspection Inspection Summary:

The site has expanded slightly from the last inspection the main pit is deeper and the footprint is very slightly larger. There were three people digging at the site at the time of the inspection. The disturbance was last GPS'ed at 4.25 acres. The current bond is not adequate to cover the amount of disturbance. Discussions have been held with the operator regarding the amount of disturbance and the lack of bond. Mr. Harris stated that he was going to perform reclamation this year. I informed him that if he did not complete reclamation this year that his bond would be escalated to cover the full five acres. The Division's current bond requirements is \$21,900 dollars.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Send a Division Directive requesting an updated surety or reclamation within 30 days.

OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

TM:pb

cc: (OPERATOR)

wstokes@blm.gov

GIS attached

O:\M027-Millard\S0270065-ML26068\inspections\insp-07172008.doc

S0270065 - Robert Harris-ML 26068 Photos taken 07/17/2008






Panaroma of main diggings.

Main pit.







Pit to the North, not currently being used.